



CgC

PATENT
Attorney's Doc. No. 5087-095

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent No.: 6,980,575
Inventor: Rohilla
Issued: December 27, 2005

For: NEW TOPOLOGY ON VCSEL DRIVER

Ser. No.: 09/801,409
Group Art Unit: 2828

Filed: March 8, 2001
Examiner: Armando Rodriquez

TRANSMITTAL LETTER

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Certificate
AUG 25 2006
of Correction

Enclosed for filing are the following:

- ☒ Request for Certificate of Correction
- ☒ Certificate of Correction Form PTO 1050 (in duplicate)
- ☒ Return postcard
- ☒ Any deficiency or overpayment should be charged or credited to deposit account number 13-1703.

Respectfully submitted,


MARGER JOHNSON & McCOLLOM, P.C.



Stephen S. Ford
Reg. No. 35,139

MARGER JOHNSON & McCOLLOM, P.C.
210 SW Morrison Street, Suite 400
Portland, OR 97204
503-222-3613

Customer No. 20575

<p>I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450</p> <p>Date: August 21, 2006</p> <p> Zach Cooper</p>

AUG 25 2006



PATENT
Attorney's Doc. No. 5087-095

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent No.: 6,980,575
Inventor: Rohilla
Issued: December 27, 2005

For: NEW TOPOLOGY ON VCSEL DRIVER

Ser. No.: 09/801,409
Group Art Unit: 2828
Filed: March 8, 2001
Examiner: Armando Rodriquez

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Upon comparison of the above-identified original Letters Patent with applicant's copy of the application therefore, the following error in the original Letters Patent has been noted:

On the cover sheet, at the title, please replace "TOPOLOGY ON VCSEL DRIVER" with -- NEW TOPOLOGY ON VCSEL DRIVER --
At column 1, line 11, please replace "TOPOLOGY ON VCSEL DRIVER" with -- NEW TOPOLOGY ON VCSEL DRIVER --

Applicant respectfully requests that a Certificate of Correction calling attention to the above error be issued pursuant to Rule 322 of the Patent Office and Title 35, United States Code, Section 254. Two copies of a Certificate of Correction form are enclosed.

Respectfully submitted,

MARGER JOHNSON & McCOLLOM, P.C.




Stephen S. Ford
35,139

MARGER JOHNSON & McCOLLOM, P.C.
210 SW Morrison Street, Suite 400
Portland, OR 97204
503-222-3613

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450

Date: August 21, 2006



Zach Cooper

AUG 25 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO : 6,980,575
DATED : December 27, 2005
INVENTOR(S) : Rohilla

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover sheet, at the title, please replace "TOPOLOGY ON VCSEL DRIVER" with -- NEW TOPOLOGY ON VCSEL DRIVER --

At column 1, line 11, please replace "TOPOLOGY ON VCSEL DRIVER" with -- NEW TOPOLOGY ON VCSEL DRIVER --

MAILING ADDRESS OF SENDER:
Marger Johnson & McCollom
210 S.W. Morrison Street, Suite 400
Portland, Oregon 97204

PATENT NO. 6,980,575

No. of additional copies
1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, D.C. 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, D.C. 20231.

AUG 25 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,980,575
DATED : December 27, 2005
INVENTOR(S) : Rohilla

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover sheet, at the title, please replace "TOPOLOGY ON VCSEL DRIVER" with -- NEW TOPOLOGY ON VCSEL DRIVER --

At column 1, line 11, please replace "TOPOLOGY ON VCSEL DRIVER" with -- NEW TOPOLOGY ON VCSEL DRIVER --

MAILING ADDRESS OF SENDER:
Marger Johnson & McCollom
210 S.W. Morrison Street, Suite 400
Portland, Oregon 97204

PATENT NO. 6,980,575

No. of additional copies
1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, D.C. 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, D.C. 20231.

NOV 23 2005